

「銀河」運用記録 "GINGA" Daily Report

198 8 MONTH : 6 DAY : 4 Y+ 486

Written by : 廿日出

Ver 1.6

OPERATION: 3C 273 & BGD

堂谷

	[PASS 1]		[PASS 2]		[PASS 3]		[PASS 4]		[PASS 5]	
NO.	880604-0617		880604-0720		880604-0824		880604-0927		880604-1031	
AOS LOS	8:13:09 8:26:04		9:55:36 10:08:09		11:37:38 11:50:11		13:19:47 13:32:14		15:02:15 15:13:44	
ELMX	21.00 19:42		58.85 01:32		天頂:		58.56 25:36		19.43 07:27	
C O M M A N D S	S H Rep BC ENA-0 01 02 BC EXE PC CLR/WRT/CHK OG-2 EXE PC STRT		ST MAP ST TRK BC ENA-1 0500007F176E BC EXE SLEW (+) PC CLR/WRT/CHK OG-2 EXE PC STRT		S H Rep BC ENA-1 0579B77A000B BC EXE MNV STRT PC CLR/WRT/CHK OG-2 EXE PC STRT		S H Rep PC CLR/WRT/CHK OG-2 EXE PC STRT ST MAP		OG-2 EXE PC CLR/WRT/CHK BC ENA-1 05CF8F530009 BC EXE MNV STRT BC ENA-1 0500007F006B BC EXE PC STRT	
	MODE	LAC	AL C A S C		AL C A S C		AL C A S C		AL C A S C	
	TLMS	Rep		Ranging		Rep		Rep		No op
	ACS	MNV continues		S (+)		MNV				MNV
LAC	MPC-1									
HV LAC ASM GBU	ON → ON → EXIT									
E V E N T			6/4 9:58 (276.23) (92.79) (9.17)		姿勢微調		6/4 13:21 (276.63) (92.76) (177.28)		10m オハシ Rep でせず 姿勢微調	
ST	8:21:59		10:05:01		11:47:01		13:29:01		15:11:18	
P C P L A N	08:24:00 OG-5 EXE 08:26:00 BIT MED 08:28:00 TMS ON 08:58:00 OG-4 EXE 09:34:00 OG-5 EXE 09:52:00 OG-1 EXE 09:54:00 OG-3 EXE		10:07:00 OG-5 EXE 10:09:00 BIT MED 10:11:00 TMS ON 10:39:00 OG-4 EXE 11:13:00 OG-5 EXE 11:35:00 OG-1 EXE 11:37:00 OG-3 EXE		11:49:00 OG-5 EXE 11:51:00 BIT MED 11:53:00 TMS ON 12:23:00 OG-4 EXE 12:53:00 OG-5 EXE 13:17:00 OG-1 EXE 13:19:00 OG-3 EXE		13:31:00 OG-5 EXE 13:33:00 BIT MED 13:35:00 TMS ON 14:07:00 OG-4 EXE 14:31:00 OG-5 EXE 14:59:00 OG-1 EXE 15:01:00 OG-3 EXE		6/04 15:12:00 BIT LOW 6/04 15:14:00 OG-5 EXE 6/04 15:16:00 TMS ON 6/04 15:48:00 OG-4 EXE 6/04 16:00:00 BIT LOW 6/04 16:10:00 OG-5 EXE 6/04 17:32:00 OG-6 EXP 6/04 17:44:00 OG-5 EXE 6/05 02:38:00 OG-4 EXE 6/05 02:40:00 OG-6 EXE 6/05 16:00:00 OG-4 EXE 6/05 16:12:00 BIT LOW 6/05 16:14:00 OG-5 EXE 6/05 16:16:00 SLEW (+) 6/06 00:46:00 OG-4 EXE 6/06 00:56:00 OG-1 EXE 6/06 00:58:00 OG-3 EXE	
C O M M E N T	・東風はレンジングなしです。 ・5パス目は 10m オハシのため Rep でせず、また PC STRT が 1分程おくれた。 4パス目と5パス目との間に BC 書き込みは行えたので、被害は最小だったと思う。 PC が短かくて良かった。 7-ナーさん ごメンナサイ (我々が悪い話ではないけれど) NEC 談 〆たぶん、サイドローフに引っかかっていたんですね									
S A M P L E	min 149.1		max 168.4		MIN. -BAT-V(EOD) 17.0 18.8 V. 18.9 18.8 V.					