

「銀河」運用記録 “GINGA” Daily Report

Ver 1.71

99 0 MONTH : 12 DAY : 23 Y+ 14/6

Written by : T. Dotani
M. Tashiro

OPERATION: MKN 335 BGD / ON SOURCE

OPERATION:		MKIN 335 BGD / ON SOURCE					
	[PASS 1]	[PASS 2]	[PASS 3]	[PASS 4]	[PASS 5]		
NO.	901223-0309	901223-0412	901223-0516	901223-0619	901223-0722		
AOS LOS	4 : 15 : 07 4 : 24 : 54	5 : 54 : 00 6 : 05 : 12	: :	9 : 12 : 58 9 : 25 : 02	10 : 53 : 04 11 : 04 : 38		
ELMX	11.24 19:43	40.10 59:10	:	72.72 18:44	27.50 58:29		
C O M M A N D S	SH Rep LC E1 ON LC E2 ON PC CLR/WRT/CHK PC STRT	Dummy Mnv BC-I 053BCI 7F0010 MNV STRT PC CLR/WRT/CHK OG-2 EXE PC STRT	Noop 10m antenna in trouble. (The azimuth-motor of the antenna did not function due to a bad contact of the control circuit board.)	SH Rep Dummy Mnv BC-I 050000 7F00E8 MNV STRT PC CLR/WRT/CHK OG-2 EXE PC STRT	SH Rep Dummy Mnv BC-I 050000 7F00E8 PC CLR/WRT/CHK PC STRT SANT-B UANT-B		
TLMS	Rep	Ranging		Rep	Rep		
ACS		Trim Mnv					
E V E N T	106.55 Frequency of the remote 53.38 148.14 106.55 Remote 53.29 148.08 106.40 After 53.23 147.81	PB 106.39 53.22 147.81	PB 106.51 53.50 148.16		PB 106.58 53.44 148.08		
ST	4 : 19 : 58	6 : 01 : 01	:	9 : 21 : 01	10 : 59 : 01		
P C P L A N	OG-5 EXE 4:22 BIT MED 4:24 TMS ON 4:26 OG-4 EXE 4:58 OG-5 EXE 5:38 OG-3 EXE 5:52	OG-5 EXE 6:03 BIT MED 6:05 TMS ON 6:07 OG-4 EXE 6:37 OG-5 EXE 7:13 OG-1 EXE 7:29 OG-3 EXE 7:31	補足説明 10m アンテナのデジタルモーターが故障したため、アンテナの受信ができず、モーターの制御装置の接触不良で、コントロールを行いたくても正常に動作しない。このため、本日に修理作業を行うことが必要と判断された。	OG-5 EXE 9:23 BIT MED 9:25 TMS ON 9:27 SLEW (-) 9:45 OG-4 EXE 9:47 MNV STRT 10:19 OG-5 EXE 10:23 OG-1 EXE 10:49 OG-3 EXE 10:51	BIT LOW 12/23 11:01 OG-5 EXE 12/23 11:05 TMS ON 12/23 11:05 SLEW (-) 12/23 11:19 OG-4 EXE 12/23 11:21 OG-6 EXE 12/23 11:31 BIT LOW 12/23 11:33 OG-5 EXE 12/23 12:01 MNV STRT 12/23 12:03 OG-6 EXE 12/23 12:57 OG-5 EXE 12/23 13:35 SLEW (-) 12/23 22:17 OG-4 EXE 12/23 22:19 OG-6 EXE 12/23 22:29 BIT LOW 12/23 22:31 OG-4 EXE 12/24 10:53 BIT LOW 12/24 11:03 OG-6 EXE 12/24 11:13 OG-5 EXE 12/24 11:35 MNV STRT 12/24 12:23 MNV STRT 12/24 12:27 OG-4 EXE 12/24 12:29 BIT LOW 12/24 12:39 OG-6 EXE 12/24 12:49 OG-5 EXE 12/24 13:07 OG-4 EXE 12/24 18:45 BIT LOW 12/24 18:55 OG-6 EXE 12/24 19:05 OG-7 EXE 12/24 19:55 SLEW 360 12/24 19:57 OG-4 EXE 12/24 20:19		
C O M M E N T	・3/バ目 10m アンテナのデジタルモーター受信できなくなった。また、5ハ入目 PC 故障で、BOR のエラーが出た。 ・先週金曜日に軌道要素が新しくなり、予報値と実際の入射差が大きくなりすぎたため、5ハ目 1分以上遅れようになった。原因が PC エラーを介してのことか不明である。 ・Merry Christmas! (この記録も25日に送る予定だが、まだ送信できていない) ※4年間の 12/24 - 12/25 には、生人から大量の電報が来るので、事前に注意しておく必要がある。 ※25日は右のとおりです。						
SANGLE 16/3 - (132.9)	STT-Y TEMP. (MAX) 14.6 °C	MIN.-BAT-V(EOD) A		18.3 V (A) 18.6 V (B)			